CODE ENFORCEMENT OFFICE TOWN OF NEWBURGH

308 GARDNERTOWN ROAD NEWBURGH, NEW YORK 12550 (845) 564-7801

ORDER TO REMEDY VIOLATION

DATE: 05/27/2011

TO: DOROTHY ESTES

43 FLETCHER DRIVE NEWBURGH NY 12550

SEC-BLK-LOT: 93-1-2.21

VIOL NO: 11-57

ORIG. COMP NO: 11-74

LOCATION: 43 FLETCHER DRIVE

PLEASE TAKE NOTICE, there exists a violation at the location described above, in that the above named individual(s) did commit or allow to exist the following offense:

SEE ATTACHED SCHEDULE A

which is in violation of:

Town of Newburgh Municipal Code

SEC: 71-8

SUB-DIV: A

TITLE: BUILDING PERMITS AND CERTIFICATES

PAGE: 71:4

Based upon the following:

SITE INSPECTION CONFIRMED A CARPORT CONSTRUCTED WITH OUT APPROVALS OR PERMITS. APPEARS TO VIOLATE LOCAL ZONING REQUIREMENTS.

YOU ARE THEREFORE DIRECTED AND ORDERED to comply with the law and to remedy the condition above mentioned forthwith on or before 106/24/2011

Failure to remedy the conditions aforesaid and to comply with the applicable provisions of law may constitute an offense punishable by fine or imprisonment or both.

JOSEPH MATTINA, Code Compliance

YOUR IMMEDIATE AND PROMPT RESPONSE TO THIS NOTICE IS MANDATORY.

TOWN OF NEWBURGH

308 GARDNERTOWN ROAD NEWBURGH, NEW YORK 12550

SEC-BLK-LOT: 93-1-2.21

PAGE: 2

DATE: 05/27/2011

LOCATION: 43 FLETCHER DRIVE

INCIDENT NO: 11-57

ORDER TO REMEDY VIOLATION
- SCHEDULE A -

IN VIOLATION OF:

Improvements or demolition. No person shall commence the construction, alteration, conversion, repair, removal or demolition of any building, structure, sign or sanitary facilities thereto, excepting agricultural equipment in existing farm structures, without first obtaining a building permit from the Building Inspector. No permit shall be required for ordinary nonstructural repairs.

Dorothy Estes 43 Fletcher Dr. Newburgh N.Y. 12550 SBL: 93-1-2.21

May 12, 2011

Mrs. Estes

A complaint has been filed for the construction of a carport with out obtaining a building permit. A site inspection conducted today affirms the compliant.

A long with this letter is a copy of that complaint.

Please respond to the Town of Newburgh Building Department no later then 5-27-2011 with a completed building permit application for this structure.

From the site inspection it appears the carport is in violation of the required minimum side yard setback for this zone. With your application submit a survey or detailed plot plan.

If you have any questions please call.

Joseph Mattina Code Compliance

01R7



To Building Drap.

CARBON 2

Sender retains Danary copy. NOTE: Send White and Pink copies. TAPLICATE

Man. Troynas

SUBSECTOS - J. D. D. D. D. L. S. L.S. TO FLETHER TH. WAS WA

DATE 5/6/11

Dunney have added a lar Portes Side of nower. (No permit

SIGNED

DATE

	EXEMPTION	TOTAL	IMPROVEMENTS	ray.		ASSESSMENT	TOTAL				ė.								, in the		nieric Signatura		1						
		2008		(0000)		330														1					17.0		- *1		
orient too		36,000		8	\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	# -₽				21 111	": 		nn.															A A	
		000		6500	1	72 2011		XOVES								, V	3+	1	3. T	2			51		A	mon New		5	
						19	Average de la constitución de la c		10-NONE	8-VIEW	7-ECONOMIC	SIZE 6-BESTBICTIONS	FRONT	2-TOPOGRAPHY 3-UNIMPROVED	CODES:	INFL UENCE			DEPTH ADJ			WARRY CONTRACTOR OF THE PROPERTY OF THE PROPER	tes Daniel		RECORD	WOOLDY N	- exclusi	tes Doro	OWNERSHIP &
->		and the second s				19]	[[) - -	VED ([[ADJUSTED INFLUENCE			Andrew Control of the	- Ma Doro		D OF OWNERSHIP	7 17850	<u>" (-</u>		MAILING
てみコン	THOU	SEWER	33 ~ ()	1 5	SCHOOL UNITY	SPECIAL DISTRICTS	- SOOO						るころう						VALUE				tus	6 67	" "				ADDRESS
		MO. YR.		FRONTING TRAFFIC:	DRIVEWAY:		SITE DESIRA	NEIGHBORHOOD	SEWER: 1-NONE 2	- WATER: 1-NONE	ROAD: 1-NONE	SITE ELEVATI	MUCK: 1 2	ELOOD BATIN	VIEW: 1-DETR	TOPOGRAPHY	ZONING: 97	NEIGHBORHOOD I.D.	SITE DESCR				07 01	E 00	MO. YS.	PROPERTY ADDRESS	CLASS CODE	SIMS	\ `
4344744		TYPE : DEMOL 2 ADDN	BUILDII	RAFFIC: 1- HEAVY	1- NONE 2- UNI	APING: 1 EXCE	Y: 1- 1	:	NONE 2-PRIVATE	NE 2-PRIVATE	ROAD: 1-NONE 2-UNIMPROVED 3	ON: 1-BELOW	4	IMS ONLY) 1-PO	IIMENTAL 2-TY	RATING: 1-GO	01 - NONE 04 02 - SINGLE RES. 04 03 - MULTI RES. 04	000 I.D.	DESCRIPTION	1 2 3	 Ю Ш	1 2 3	1 2 6	1 2/3	31%B 2 BLDG		CARD NUMBER	s [) A
	A Control of the Cont	AMOUNT	BUILDING PERMIT RECORD	AVY 2- MEDIUM 3- LIGHT	2- UNIMPROVED 3- IMPROVED		SITE DESIRABILITY: 1- INFERIOR 2- TYPICAL		3-COMM/PI 3-ELECTRIC	3-Q	ROVED 3-IMPROVED	SITE ELEVATION: 1-BELOW GRADE 2-LEVEL 3-ABOVE		ELOOD BATING: 1-ALWAYS 2-MIXED 3-DETEN 4-SOME S-MEYER	VIEW: 1-DETRIMENTAL 2-TYPICAL 3-ENHANCING	TOPOGRAPHY RATING: 1-GOOD 2-FAIR 3-POOR 4-VERY POOR	04 - FARM 07 - N 05 - COMMERCIAL 08 - C 06 - INDUSTRIAL		SITE	**************************************		<u> </u>	1 1 2	00011	SALE PRICE	Yer.	m	8 7	PROPERTY IDENTIFICATION
		NUMBER		С €	NOVED	FAIR 4 POOR 5 NONE	2- SUBURBAN 3- URBAN 4- COMMERCIAL		4-GAS AND ELECTRIC		WED	ABOVE GRADE		GOOD COOD	G	4-VERY POOR	07 - MIXED 08 - GOVERNMENT		PROPERTY CLASS	1 2 3 4 5 1 2	ω ω 4 ω	12345 12	12345 1(2)	1 2 3 4 5 7 2	1 UNCONFIRMED VALIDITY 2 BUYER 4 FEE 1 YES 3 SELLER 5 AGENT 2 NO	<u>.</u> }	GRID COORDINATE		NON TION

349		3	2/2	11.7	CODE CODE • 1 2 TITY - BUILT	CHED IMPROVEMENTS	STONE/BRICK 1 YES	MASONARY TRIM (SF)	2 AVERAGE	S	STYLE OF BATH:	STYLE OF KITCHEN: KITCHEN QUALITY:	NUMBER OF KITCHENS:	PLUMBING: 1 YES NO	AIR CONDITIONING: 1 YES	1 NONE 3 ELECTRIC 5 WOOD 7 COAL C	1 NO CENTRAL 2 HOT AIR 3 STEAM/HOT WATER 4 ELECTRIC	B 2 CRAWL 3 PARTIAL 4 FULL	FAMILY TOTAL		AGE: YEAR BUILT REMODELED EFFECTIVE YR BUILT	VINYL 6STUCCO	LLS: IE 4 COMPOSITION 7 STONE 5 CONCRETE	NUMBER OF STORIES / O	06 CONTEMPORARY 11 LOG CABIN NCH 07 MANSION 12 DUPLEX EL 08 OLD STYLE 13 BUNGALOW 09 COTTAGE 14 OTHER
3 /US PEMI + TOTAL OTAL TOTAL .	DET. IMPROV.		١ (77 0880	TOTAL	GRADE ADJ.	TOTAL BASE	HEATING/AC	ATTIC	BSMT FINISH	BASEMENT	PLUMBING	BASE PRICE	NOTES:	RECREATION BOOM (SF)	-	FINISHED ATTIC (SF) FINISH OVER GARAGE (SF)	THREE QUARTER STORY UNFIN. (SF) FINISHED BASEMENT (SF)	HALF STORY UNFINISHED (SF) THREE QUARTER STORY FIN. (SF)	HALF STORY FINISHED (SF)	2007 312	LIVING AREA: FIRST FLOOR (SF)	FUNCTIONAL/ECONOMIC OCSOLESCENSE CDU (EX, VG, G, AV, P, VP, UN)	GRADE GRADE AOJ. TERRETE GOOD	INTERIOR CONDITION EXTERIOR CONDITION 1 POOR 2 FAIR 3 NORMAL 4 GOOD 5 EXCELLANT
	70	9	8	7	000		5		3/80 / 01 2	2 155 3 433 / 01 7 3		CODE CODE . 1 2 TITY BUILT. RATE 1 0850	CHED IMPROVEMENTS			303) S-0)									

CODE ENFORCEMENT OFFICE TOWN OF NEWBURGH 308 GARDNERTOWN ROAD NEWBURGH, NEW YORK 12550 (845) 564-7801

NOTICE OF COMPLAINT

DATE: 05/06/2011

TO: DOROTHY ESTES 43 FLETCHER DR

NEWBURGH

SEC-BLK-LOT: 93-1-2.21

COMPL=NO: 11-74

LOCATION: 43 FLETCHER DRIVE

PLEASE TAKE NOTICE, a complaint has been registered against the location described above, in that the above named individual(s) did commit or permit to occur the following offense:

SEE ATTACHED SCHEDULE A

YOU ARE THEREFORE DIRECTED AND ORDERED to contact this office immediately to arrange for an inspection of the above described condition.

Failure to promptly comply with this directive may result in a fine or imprisonment or both

CODE ENFORCEMENT OFFICE TOWN OF NEWBURGH

308 GARDNERTOWN ROAD NEWBURGH, NEW YORK 12550

SEC-BLK-LOT: 93-1-2.21

PAGE: 2

DATE: 05/06/2011

LOCATION: 43 FLETCHER DRIVE

COMP NO: 11-74

NOTICE OF COMPLAINT
- SCHEDULE A -

COMPLAINT:

BUILT A CARPORT TO SIDE OF HOUSE, NO PERMIT ON FILE